

# VI WASHING DRIVER WD3DV07

<https://www.aliexpress.com/i/32536688447.html>



**W** 华兴数控  
WASHING

● 正常  
● 报警

电流3  
电流2  
电流1  
电流0  
半流  
联机  
细分2  
细分1  
细分0  
单脉冲

步数	细分2	细分1	细分0
1000	ON	ON	ON
2000	ON	ON	OFF
4000	ON	OFF	ON
8000	ON	OFF	OFF
16000	OFF	ON	ON
32000	OFF	ON	OFF
64000	OFF	OFF	ON
128000	OFF	OFF	OFF

脱机+  
方向-  
方向+  
脉冲-  
脉冲+

全流  
脱机  
双脉冲  
出错-  
出错+  
脱机

频率(A)	电流3	电流2	电流1	电流0
6.3	ON	ON	ON	ON
6.4	ON	ON	ON	OFF
6.5	ON	ON	OFF	ON
6.6	ON	ON	OFF	OFF
6.2	ON	OFF	ON	ON
6.8	ON	OFF	ON	OFF
6.5	ON	OFF	OFF	ON
6.7	ON	OFF	OFF	OFF
3.7	OFF	ON	ON	ON
3.8	OFF	ON	ON	OFF
2.9	OFF	ON	OFF	ON
2.5	OFF	ON	OFF	OFF
2.2	OFF	OFF	ON	ON
1.8	OFF	OFF	ON	OFF
1.4	OFF	OFF	OFF	ON
1.0	OFF	OFF	OFF	OFF

A相 —  
B相 —  
C相 —

AC220V —  
AC220V —

PE —

三相混合式  
步进电机驱动器  
型号: WD3DV07

**警告**

1. AC220V输入必须加隔离变压器
2. PE端必须良好接地

南京华兴数控技术有限公司

**DESCRIPTION CUSTOMER REVIEWS (0)  
SPECIFICATIONS**

**Report Item**

**Phase hybrid stepping motor driver WD3DV07**

**Power supply**

**Single-phase 220V 15a%, 50 / 60HZ,  
capacity 350VA / shaft**

**Output Current 1 ~ 6.8A (rms)**

**Drive mode**

**Three-phase PWM, half current lock**

**Matching motor**

**90BYG, 110BYG, 130BYG mixed-phase three-wire  
stepper motor step**

**Excitation mode**

**1000,2000,3000,4000,5000,6000,10000,12000 steps / rev**

**cooling method**

**External Forced air**

**weight**

**1.5-2.0KG**

**Tel: 15923222093**